



July 1, 2021

Kenneth Wayne Jones
County Administrator
Hinds County
Post Office Box 686
Jackson, MS 39205-0686

Re: Benchmark Invoice #30

Dear Mr. Jones:

Please find enclosed our invoice for June 2021. I have attached timesheets as well as a breakdown by facility for your reference. Please process for payment.

If you have any questions please let me know.

Sincerely,

David Marsh,
President





1867 Crane Ridge Dr., Suite 200-A
 P.O. Box 31177 Jackson, MS 39286-1777
 Phone (601) 362-6110
 Fax (601) 362-9812

INVOICE

NO. 30
07/01/2021

DATE: _____

YOUR ORDER NO. N/A

SOLD TO: Hinds County

LOCATION: Raymond Detention Center
 Work Center/Jackson D C
 Henley - Young

OUR JOB NO.:	CONTRACT DATE: 03/26/20	AUTHORIZED BY: B.O.S.
DESCRIPTION	AMOUNT	
INVOICE FOR JUNE 2021		
David Marsh	\$ 3,358.00	
Gary Chamblee	\$12,848.00	
Willie Edmond	\$10,584.00	
Timesheets Attached		
TOTAL AMOUNT THIS INVOICE		\$26,790.00

• PLEASE PAY FROM INVOICE • NO STATEMENT RENDERED •

HINDS DETENTION FACILITIES
TIME SHEET RECAP

7/1/2021	6/30/2021 DESCRIPTION	HOURS	AMOUNT	TOTAL
	RAYMOND DETENTION CENTER			
	Gary Chamblee	122	\$73	\$ 8,906.00
	Willie Edmond	171	\$56	\$ 9,576.00
		293.00		\$ 18,482.00
	HENLEY YOUNG			
	Willie Edmond	18	\$56	\$ 1,008.00
	Gary Chamblee	30	\$73	\$ 2,190.00
		48		\$ 3,198.00
	WORK CENTER			
	Willie Edmond	0	\$56	\$ -
	Gary Chamblee	24	\$73	\$ 1,752.00
		24		\$ 1,752.00
	JACKSON DETENTION CENTER			
	Gary Chamblee	0	\$73	\$ -
	Willie Edmond	0	\$56	\$ -
		0		\$ -
	MEETINGS			
	David Marsh	46	\$73	\$ 3,358.00
		46		\$ 3,358.00
	TOTAL			\$ 26,790.00
	TOTAL AMOUNT DUE			\$ 26,790.00

HINDS DETENTION FACILITIES
TIME SHEET DAVID MARSH

DATE	Jun-21 DESCRIPTION	HOURS
Meeting 2-Jun	Meeting/Review projects	2.00
Meeting 3-Jun	Meeting/Review projects	4.00
Meeting 4-Jun	Meeting/Review projects	2.00
Meeting 7-Jun	Meeting/Review projects	4.00
Meeting 9-Jun	Meeting/Review projects	4.00
Meeting 10-Jun	Meeting/Review projects	1.00
Meeting 11-Jun	Meeting/Review projects	6.00
Meeting 14-Jun	Meeting/Review projects	3.00
Meeting 16-Jun	Meeting/Review projects	3.00
Meeting 17-Jun	Meeting/Review projects	2.00
Meeting 18-Jun	Meeting/Review projects	2.00
Meeting 21-Jun	Meeting/Review projects	3.00
Meeting 23-Jun	Meeting/Review projects	2.00
Meeting 24-Jun	Meeting/Review projects	1.00
Meeting 28-Jun	Meeting/Review projects	3.00
Meeting 29-Jun	Meeting/Review projects	3.00
Meeting 30-Jun	Meeting/Review projects	1.00
		<hr/> 46.00

46 TOTAL MEETING HOURS x \$73 = \$ 3,358.00

HINDS DETENTION FACILITIES
TIME SHEET GARY CHAMBLEE

DATE	DESCRIPTION	RDC	WC	HY	JDC	TOTAL
1-Jun	RDC/WORK CENTER	6		2		
2-Jun	RDC	8				
3-Jun	RDC/COMPLIANCE MEETING	6			2	
4-Jun	RDC WORK ORDERS/RDC PROPOSAL/	6			2	
7-Jun	RDC WORK ORDERS/COMPLIANCE MEETING	6			2	
8-Jun	RDC/WORK CENTER	6		2		
9-Jun	RDC/WORK CENTER	6		2		
10-Jun	RDC WORK ORDER/WORK CENTER	6		2		
11-Jun	RDC WORK ORDERS/MAINTENANCE DIRECTOR LEE	8				
14-Jun	RDC PROPOSAL/PROPOSALS/	6			2	
15-Jun	HINDS COUNTY/ WORK ORDERS/ CONSENT DECREE	4		2	2	
16-Jun	HINDS COUNTY COMPLIANCE MEETING	4		2	2	
17-Jun	HINDS COUNTY WORK ORDERS/ PROPOSALS	6		2		
18-Jun	HINDS CO WORK ORDERS/RDC/WORK CENTER/HENLEY YOUNG	4		2	2	
21-Jun	HINDS COUNTY WORK ORDERS/ RDC PROPOSAL/LEE	6		1	1	
22-Jun	RDC/HENLEY YOUNG	4			4	
23-Jun	RDC/HENLEY YOUNG/B&E	6			2	
24-Jun	RDC/WORK CENTER	6		2		
25-Jun	RDC/WORK CENTER	6		2		
28-Jun	RDC/HENLEY YOUNG/WORK CENTER	4		2	2	
29-Jun	RDC/HENLEY YOUNG/WORK CENTER	3		1	4	
30-Jun	RDC/HENLEY YOUNG	5			3	
TOTAL HR JUNE 2021		122	24	30	0	176

BENCHMARK CONSTRUCTION CORPORATION

D-000219

HINDS DETENTION FACILITIES
TIME SHEET WILLIE EDMOND

	DATE	6/30/2021 DESCRIPTION	HOURS
RDC	1-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	2-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	3-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	4-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	7-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	8-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	9-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	10-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	11-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	14-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	15-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	17-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	18-Jun	ON SITE. WORK ORDER REVIEW.	9.00
HY	21-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	22-Jun	ON SITE. WORK ORDER REVIEW.	9.00
HY	23-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	24-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	25-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	28-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	29-Jun	ON SITE. WORK ORDER REVIEW.	9.00
RDC	30-Jun	ON SITE. WORK ORDER REVIEW.	9.00
		TOTAL RDC HOURS	189.00

189 TOTAL HOURS x \$56 = \$ 10,584.00
\$ 10,584.00



Daily Report

Thursday, Jun 03, 2021

Raymond Work Center

1450 County Farm Road
Raymond, Ms 39154



WEATHER


Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:59 AM	73°F	100%	N	0 MPH	3 MPH	0 IN	Cloudy
06:06 AM	70°F	100%	N	0 MPH	3 MPH	0 IN	Fog
10:07 AM	79°F	94%	N	0 MPH	2 MPH	0 IN	Sunny
02:09 PM	82°F	61%	N	0 MPH	3 MPH	0 IN	Partly sunny
05:58 PM	84°F	61%	WNW	8 MPH	8 MPH	0 IN	Mostly cloudy
09:59 PM	73°F	100%	N	0 MPH	1 MPH	0 IN	Cloudy

NOTES

10:14 AM Wille Edmond
[Lat/Long: 32.245621,-90.400640]


JL Roberts demo old rooftop unit #6 and installed new one at Work Center for housing unit 1





04:48 PM Wille Edmond
[Lat/Long: 32.244354,-90.403617]

Lewis Fire Protection wire up jockey pump and turn on system and said that the system has a somewhere



Employee Signature: _____



Daily Report

Thursday, Jun 03, 2021

Raymond Detention Center

1450 County Farm Rd
Raymond, MS 39154

WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:59 AM	73 °F	100%	N	0 MPH	3 MPH	0 IN	Cloudy
06:06 AM	70 °F	100%	N	0 MPH	3 MPH	0 IN	Fog
10:07 AM	79 °F	94%	N	0 MPH	2 MPH	0 IN	Sunny
02:09 PM	82 °F	61%	N	0 MPH	3 MPH	0 IN	Partly sunny
05:58 PM	84 °F	61%	WNW	8 MPH	8 MPH	0 IN	Mostly cloudy
09:59 PM	73 °F	100%	N	0 MPH	1 MPH	0 IN	Cloudy

LABOR - REPORTED BY BENCHMARK CONSTRUCTION


Name	Cost Code	Trade	Class	Worker(s)	Hours	Description
CML Security				1	8.00	installed UPS systems at booking and c pod
Total:				1	8.00	



NOTES


04:55 PM Wille Edmond
[Lat/Long: 32.244381,-90.403652]

Lewis Fire Protection wired jockey pump and replaced flanges and turn on system











Daily Report

Tuesday, Jun 08, 2021

Raymond Detention Center

1450 County Farm Rd
Raymond, MS 39154

WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:58 AM	72 °F	100%	N	0 MPH	6 MPH	0.04 IN	Cloudy
06:07 AM	73 °F	100%	ESE	4 MPH	8 MPH	0 IN	Cloudy
10:05 AM	82 °F	100%	S	9 MPH	9 MPH	0 IN	Cloudy
01:59 PM	90 °F	89%	SSW	12 MPH	19 MPH	0 IN	Mostly cloudy
05:58 PM	86 °F	100%	S	3 MPH	9 MPH	0 IN	Partly sunny
09:58 PM	79 °F	100%	SSE	4 MPH	4 MPH	0 IN	Cloudy

LABOR - REPORTED BY BENCHMARK CONSTRUCTION

Name	Cost Code	Trade	Class	Worker(s)	Hours	Description
Hinds County Plumber				1	0.00	work on plumbing problems in b-pod cells
Total:				1		



Daily Report

Wednesday, Jun 09, 2021

Raymond Detention Center

1450 County Farm Rd
Raymond, MS 39154

WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip Condition
01:58 AM	77 °F	100%	SSE	3 MPH	11 MPH	0 IN Mostly clear
06:06 AM	75 °F	100%	ESE	3 MPH	7 MPH	0 IN Mostly cloudy
09:59 AM	82 °F	100%	SW	9 MPH	11 MPH	0 IN Cloudy
01:59 PM	86 °F	100%	NNW	8 MPH	11 MPH	0 IN Mostly cloudy
05:59 PM	86 °F	100%	SE	3 MPH	8 MPH	0 IN Cloudy
09:58 PM	70 °F	100%	ESE	7 MPH	8 MPH	0.35 IN Light rain

NOTES

07:07 PM Wille Edmond
[Lat/Long: 32.323174,-90.072520]

Hinds County Maintenance open welded doors, cleaned trash out of them, checked for breaching and toilet, sink operating. welded doors back that were not working and metal plates at bottom of doors and missing glasses to keep inmates from throwing trash in A-2 pod

'A-2 Pod' Bottom Tier

Doors-5175-Open, Cleaned and left open

5177-*****

5178-Open door, cleaned, found hole in cell at chase

wall. Welded door back

5183-open, cleaned and also found hole in cell.

welded door back

5184-open, cleaned and left open

5185-open, cleaned and found sink not

working. welded door back and welded

metal plate at glass

5187-open, cleaned and left open

5189-open, cleaned and found hole in cell at chase

wall. welded door back and secured window

and door from trash being put in

Top Tier

5550-open door, cleaned and found hole in cell at

chase wall. welded door back

5556-door was welded and secured from trash to


be put in...Leroy Lee and Capt Cannon said



to leave as is and to concentrate on the cells





with trash in for now



5560-open, cleaned and left open
























Daily Report

Thursday, Jun 10, 2021

Raymond Detention Center

1450 County Farm Rd
Raymond, MS 39154

WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip Condition
01:58 AM	73 °F	100%	N	4 MPH	9 MPH	0 IN Cloudy
06:06 AM	75 °F	100%	SSW	8 MPH	11 MPH	0 IN Mostly cloudy
09:59 AM	79 °F	100%	WNW	4 MPH	8 MPH	0.04 IN Cloudy
01:58 PM	75 °F	100%	N	0 MPH	4 MPH	0.07 IN Light rain
05:58 PM	75 °F	100%	N	0 MPH	6 MPH	0.08 IN Cloudy
09:58 PM	73 °F	100%	N	0 MPH	2 MPH	0 IN Partly cloudy

NOTES

07:28 PM Wille Edmond
[Lat/Long: 32.323287,-90.872245]

Hinds County Maintenance open welded cells doors, cleaned, checked for breaching, checked toilets and sinks operating properly, welded doors back and secured from trash in A-1, and A-3

A-1 open, cleaned and welded back, secured from trash

Doors

5158, 5159, 5166, 5167, 5533, 5534

A-3 Doors

5108-could not get door open..welded door back and
secured from trash

5112-no trash in..left welded and secured from trash


5505



5511





5504-open welded cells doors, cleaned, found holes in walls


5507 welded doors back and secured from trash

5512









Welded Doors In A-Pod
*A-1 Doors *
5158,5159,5166,5167,553
3,5534
A-2
5175,5177,5178,5183,518
4,5187,5189,5550,5556,5
560
A-3
5108,5112,5504,5505,55
07,5511,5513
A-4
5124,5125,5126,5135,552
0,5526




07:47 PM Wille Edmond

[Lat/Long: 32.323173,-90.872277]

JL Roberts and HCM assisted on opening a/c welded doors in A-1 and A-3 unit to check out why it's hot

A-2,A-4 and pod control units still have pneumatic valves

A-3 has hole in duct at unit from breach..





Daily Report

Tuesday, Jun 15, 2021

Raymond Detention Center

1450 County Farm Rd
Raymond, MS 39154

WEATHER


Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip Condition
01:59 AM	75 °F	100%	N	0 MPH	2 MPH	0 IN Mostly clear
06:05 AM	72 °F	100%	N	0 MPH	3 MPH	0 IN Fog
09:58 AM	86 °F	94%	N	3 MPH	3 MPH	0 IN Sunny
02:09 PM	91 °F	55%	N	0 MPH	14 MPH	0 IN Sunny
05:58 PM	91 °F	55%	N	3 MPH	11 MPH	0 IN Sunny
09:54 PM	77 °F	100%	N	0 MPH	5 MPH	0 IN Partly cloudy

NOTES

07:33 PM Wille Edmond
[Lat/Long: 32.323318,-90.872575]

JL Roberts repaired holes in a/c duct..one in A-3 and one in A-2, both holes at unit







07:45 PM Wille Edmond

[Lat/Long: 32.323197,-90.872700]

JL Roberts demo old and installed new a/c duct damper in A-2 unit at a/c unit







Daily Report

Wednesday, Jun 16, 2021

Raymond Detention Center

1450 County Farm Rd
Raymond, MS 39154

WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:59 AM	75 °F	100%	N	0 MPH	6 MPH	0 IN	Clear
05:58 AM	68 °F	100%	N	0 MPH	4 MPH	0 IN	Mostly sunny
10:05 AM	82 °F	61%	N	4 MPH	4 MPH	0 IN	Sunny
01:59 PM	86 °F	42%	N	4 MPH	11 MPH	0 IN	Sunny
05:54 PM	86 °F	43%	ENE	5 MPH	8 MPH	0 IN	Sunny
09:58 PM	72 °F	100%	N	0 MPH	3 MPH	0 IN	Partly cloudy


NOTES

04:51 PM Wille Edmond
[Lat/Long: 32.323240,-90.872451]

JL Roberts demo and installed air handler pulley on B-2 unit

04:56 PM Wille Edmond
[Lat/Long: 32.323238,-90.872534]

Damaged duct in A-4 unit that's stopping properly air flow







Video Files:

- [E9688C5B-FEC5-4BDB-8E07-E57C42D694DD.mp4](#)
- [E431347F-79CC-4280-ACCE-37582F2B7A24.mp4](#)



Daily Report

Monday, Jun 21, 2021

Henley-Young Juvenile Justice

940 E McDowell Rd
Jackson, MS 39204

WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:59 AM	81 °F	76%	SW	14 MPH	23 MPH	0 IN	Cloudy
06:06 AM	76 °F	87%	S	7 MPH	9 MPH	0 IN	Cloudy
10:09 AM	78 °F	78%	SSW	10 MPH	12 MPH	0 IN	Cloudy
01:59 PM	86 °F	60%	SSW	10 MPH	10 MPH	0 IN	Mostly sunny
05:58 PM	75 °F	83%	WNW	11 MPH	37 MPH	0.09 IN	Thunderstorm
09:58 PM	71 °F	89%	SSW	16 MPH	25 MPH	0.61 IN	Cloudy

LABOR - REPORTED BY BENCHMARK CONSTRUCTION



Name	Cost Code	Trade	Class	Worker(s)	Hours	Description
B & E Communication				2	8.00	Demo old pod control boards and pull new wires
Total:				2	8.00	

NOTES

11:45 PM Wille Edmond
[Lat/Long: 32.323245,-90.872527]

B&E Communication demo old doors control system and pull wires for new system





Employee Signature: _____



Daily Report

Wednesday, Jun 23, 2021

Henley-Young Juvenile Justice

940 E McDowell Rd
Jackson, MS 39204

WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:59 AM	68 °F	87%	N	0 MPH	1 MPH	0 IN	Mostly clear
05:58 AM	72 °F	78%	E	4 MPH	4 MPH	0 IN	Cloudy
10:06 AM	77 °F	70%	ESE	6 MPH	6 MPH	0 IN	Cloudy
02:06 PM	88 °F	58%	NE	4 MPH	4 MPH	0 IN	Cloudy
05:58 PM	88 °F	60%	N	3 MPH	3 MPH	0 IN	Mostly cloudy
09:59 PM	82 °F	73%	N	0 MPH	3 MPH	0 IN	Mostly cloudy

LABOR - REPORTED BY BENCHMARK CONSTRUCTION

Name	Cost Code	Trade	Class	Worker(s)	Hours	Description
B & E Communication				2	8.00	Demo old wire and pull new wires from pod control to central control
Total:				2	8.00	

Employee Signature: _____



Daily Report

Tuesday, Jun 29, 2021

Raymond Work Center

1450 County Farm Road
Raymond, Ms 39154


WEATHER

Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:59 AM	72 °F	100%	N	0 MPH	4 MPH	0 IN	Mostly clear
05:58 AM	70 °F	100%	N	0 MPH	3 MPH	0 IN	Clear
10:08 AM	84 °F	100%	SE	6 MPH	6 MPH	0 IN	Partly sunny
02:08 PM	90 °F	74%	N	4 MPH	7 MPH	0 IN	Mostly sunny
05:59 PM	86 °F	78%	S	9 MPH	19 MPH	0 IN	Partly sunny
09:59 PM	75 °F	100%	ESE	3 MPH	6 MPH	0 IN	Mostly cloudy

NOTES

11:47 PM Wille Edmond
[Lat/Long: 32.323147,-90.872381]

Lewis Fire Protection demo old and installed new ball valve, address all other leaks and inspected and pass entire sprinkler system





Employee Signature: _____



Daily Report

Tuesday, Jun 29, 2021

Raymond Detention Center

1450 County Farm Rd
Raymond, MS 39154

WEATHER


Time	Temp	Hum	W-Dir	W-Speed	W-Gust	Precip	Condition
01:59 AM	72 °F	100%	N	0 MPH	4 MPH	0 IN	Mostly clear
05:58 AM	70 °F	100%	N	0 MPH	3 MPH	0 IN	Clear
10:08 AM	84 °F	100%	SE	6 MPH	6 MPH	0 IN	Partly sunny
02:08 PM	90 °F	74%	N	4 MPH	7 MPH	0 IN	Mostly sunny
05:59 PM	86 °F	78%	S	9 MPH	19 MPH	0 IN	Partly sunny
09:59 PM	75 °F	100%	ESE	3 MPH	6 MPH	0 IN	Mostly cloudy

NOTES

11:53 PM Wille Edmond

[Lat/Long: 32.323199,-90.872382]

Inspected and tested entire sprinkler system at RDC







EXHIBIT NO. D-13
CAUSE NO. 3:16-cv-00489-CWR-BWR
WITNESS B. Chamblee
CLERK: TWANA SUMMERS

FEB 24 2022

UNITED STATES DISTRICT COURT
SOUTHERN DISTRICT OF MISSISSIPPI
Candice Crane REPORTER